

FEB 01 1982

DPM 3236

Budget 1/1/82



TIBBETTS-WESTERFIELD PAINT CO., INC. 2600 East 8th Street, Los Angeles, California 90023, (213) 264-4710

January 20, 1978

Mr. J. J. Veneroso
Dept. C1-726 (52-11)
Materials Handling & Packaging Engineering
Douglas Aircraft Company

Dear Mr. Veneroso,

None of the items in your letter of January 16, 1978 are regulated or restricted articles.

Very truly yours,

R. S. Kelsey

Richard S. Kelsey
Vice President

RSK/tv

DOUGLAS AIRCRAFT COMPANY

3855 Lakewood Boulevard Long Beach, California 90846

January 16, 1978

C1-725-17

T. W. Screen Process Supply Company
2600 East 8th Street
Los Angeles, California 90023

Gentlemen:

This facility must, on occasion, reship your following products:

Butyl Lactate - *DPM 3236*
Vinyl Paint, TW-9500-66 Series - *DPM 3248*
Coatings 323A, 344A and S-334A - *DPM 5859*

In order to insure our compliance with the Hazardous Materials Regulations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your products are regulated or restricted articles for shipment by surface or air modes of transport.


Should the products be regulated, please indicate:

1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
2. DOT Hazard Classification per Section 172.101, 49 CFR.
3. Flash Point and Closed Cup method per Section 173.115, 49 CFR.
4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet, if available, for all components listed.

Your cooperation and prompt reply will be appreciated.

Very truly yours,



M. J. Veneroso, Dept. C1-726 (52-11)
Materials Handling & Packaging Engineering
Douglas Aircraft Company

WTJ:rc

MCDONNELL DOUGLAS

CORPORATION

BOE-C6-0204807